



| REVISIONS |     |      |         |         |
|-----------|-----|------|---------|---------|
| ISSUE     | SYM | DATE | DRAFTER | CHECKER |
|           |     |      |         |         |
|           |     |      |         |         |
|           |     |      |         |         |

NOTE:



树林企业股份有限公司  
TAIWAN SHULIN ENTERPRISE CO., LTD

WEB:www.bobbin.com.tw

e-mail:shulin@bobbin.com.tw

(TAIWAN TAIPEI) TEL:(886)2-2223-1500 FAX:(886)2-2222-4646

(CHINA DONGGUAN) TEL:(86)769-7730-785 FAX:(86)769-7312-387

(CHINA SUZHOU) TEL:(86)512-6621-0580 FAX:(86)512-6621-0685

|              |            |  |    |
|--------------|------------|--|----|
| MODEL        |            | TF-3102  |    |
| MATERIAL     |            | PHENOLIC(T375J)  |    |
| UL RATING    | UL94V-0    | TOLERANCE<br>.X ± 0.2<br>.XX ± 0.15<br>PIN PITCH ± 0.1 |    |
| PIN MATERIAL | CP WIRE    |  |    |
| EDITION      | 1.0        |  |    |
| DATE         | 2008/09/05 |  |    |
| SCALE        | 1.5/1      | UNIT   | MM |